

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Supervisor

Inspection Report Minerals Regulatory Program

Report Date: February 3, 2010

	• /			
Mine Name: Italian Tan	Permit number: S/007/038			
Operator or Permittee Name:	Inspection Date: February 3, 2010			
Quality Building Stone				
Permittee Mailing Address:				
933 W. 14730 S., Bluffdale, Utah 84065				
		•	ear with6-8" of	
			ature in the 30s	
Inspector(s): Wayne Western	Inspection Start Time: 2:00 PM			
			ne: 3:00 PM	
Other Participants: None	Site loc	ation/Area l	inspected (i.e.	Pit #):
	Entire s	ite.		
Permit Status: Permitted	Surface	Ownership	: Fee (with adj	acent
	BLM)			
Current Acreages: 2.0 acres	Minera	l Ownership	: Fee (with adj	acent
	BLM)			
Total Permitted (Bonded): 2.00		l Mined: Bu		
Total Disturbed: 1.0	Type of	Mine: Surfa	ace	
	E141	NT/A	Commont	Enforcement
Elements of Inspection	Evaluated	N/A	Comment	Emorcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes	Ш		
2. Public Safety (open shafts, adits, trash,				
signs, highwalls)				
3. Protection of Drainages	H	H	H	님
4. Explosives, magazines	H	H	H	H
5. Deleterious Material				
6. Roads (maintenance, surfacing, dust control,				
safety) 7. Concurrent Reclamation				
8. Erosion Control	H	H	H	H
9. Demolition	H	H	H	H
10. Backfilling and Grading (trenches, pits,				
• • • • • • • • • • • • • • • • • • • •	\boxtimes		\boxtimes	
roads, highwalls, shafts, drill holes) 11. Water Impoundments				
12. Soils	H	H	H	H
13. Revegetation	H	H	H	H
14. Air Quality	H	H		H
15. Facilities	H	H	H	H
	닐			\vdash
16. Other	\boxtimes		\boxtimes	
				UTAH
				DNR

Inspection Date: June 9, 2005; Report Date: June 23, 2005

Page 2 of 2 S/007/038

Purpose of Inspection:

The purpose of the inspection was to determine if site conditions would allow the Division to release the bond and retire the site. The area had 6-8 inches of snow on the ground. The amount of disturbance was small and the area appeared to be reclaimed. However, due to the amount of snow on the ground, the Division was unable to conduct a adequate bond release inspection. Due to the amount of snow on the ground pictures of the site were not included in the inspection report.

Conclusions/Recommendations:

The Division should conduct

an additional inspection when there is no snow on the ground.

Inspector's Signature Warne Wallet

Date: February 4, 2010

WW:jb

cc: Dam Powell Quality Building Stone

O:\M007-Carbon\S0070038-ItalianTan\inspections\ins-02032010.doc